

Jan 7, 2016 3-11 Shift Notes

BASF EMPLOYEES

45 Last Recordable
100 Last Lost time

SAFETY Notes: Check the walkways for ice and treat with icemelt. Some slippery spots have been found around the site, especially near roof gutter downspouts.

Title V Notes: <u>Trimer</u> – Trimer is on ORP. The Chem tank probe has been replaced. See your Group Leader if you have any questions. <u>CTO</u> – is still in manual, continue to stay above 25% SP or it will kick out

#1 MED / D 0713:

Got recipe loaded starting up on day shift.

Do not increase the speed on the extruder to above 60 hz until IMC can correct the issue. Still need low level probe on miners installed, but is not needed for this product.

#1 RC / Clean for D 0713:

Started feeding late on day shift. Holding pfaudler to run calciner.

#2 MED line / Styrene next

Installed auger #28. Auger #13 is on the floor behind #2 extruder and can be used next when we need a change out about 100,000# into the run.

Need to finish vacuuming out the bottom of the mixer. The other portion of Justin's e-mail was completed.

WOW for plugged drain. Line to start around the 11th.

Powder room scales have been calibrated.

#2 RC/:

Okay to start cleanup.

#3 MED line / AL 3945:

Continue making batches. Upped acid from 25 to 27 #'s.

Please keep a close eye on the ammonia and nitric additions over the next few shifts when we restart.

#3 RC / AL-3945:

Continue feeding. Cutter disconnect hammer was fixed so that a LOTO could be performed. WOW to replace.

#4 RC / Cu-0226:

Holding for more material.

There is one bag of the next size material that has been repacked and is staged by #4 RC. Hold this bag until we start up the next run.

#5 RC / Catoxid:

Feed started back up on day shift. Purge air regulator was functioning properly as it was programmed. Found the damper was almost shut on DC. Got opened back up.

#6 RC & Dryer / D 0765 then Cleaning:

Continue clean up.

Last partial drum has been hand-picked and is 37 lbs. It is sitting by #6 calciner. The suction gauge was recalibrated. It is currently reading .07. Keep an eye on the suction. The suction/syntron cutoff in the control room was changed to -.10 in order to compensate for the change.

West Pfaudler / D 4601

Continue drying and should be ready to start cooling on second shift. Then holding so that we can run #1 RC.

East Pfaudler/ Cleaning:

Pfaudler has been cleaned and lid has been put back on.

6 Tank: Tank empty

Valve fixed. There was a screen and band clamp in the valve.

7 Tank: D-0226 Solution

Pumped out the solution in this tank. We have 2 totes worth on the 2nd floor to be used in the next run.

National Dryer / D-5206.

Schirmer finished soda blasting. Hold for next product.

PK Blender / Catoxid

PK is leaking from the shower caps need to T/S further. Holding until problem is resolved.

Use Cardboard sleeves for all bags. All bags are to be only filled ¾ full to prevent overfilling and spills. Please do not use water to seal caps or end seals. If we have issues with the blender leaking stop production and we will address the issues.

Dust collector can be blown down by switching the magnahelic gauge to 0 and then shutting off the blower when it starts to blow down.

DC gauge has been added to the Wonderware and has been moved over to near the weight tank. Gauge should be set at 3.5 and 4.25

Abbe Blender / D 5206:

HF tote has been closed up and Abbe lid was remove and vessel cleaned out. Cover plates over open hole in floor have been reinstalled.

Tower 3 / Al 5645:

Done with testing do not need to staff

Tower 6 / AI 5645:

Done with testing do not need to staff.

Repacking in screening room:

North Screener / DPT-0101:

Cleaning??

South Screener / DPT-0101:

Cleaning??

#2662 (west) Pill Machine /

Back together and holding.

#2664 (east) Pill Machine /

Back together and holding.

TK #2 / down:

Unloaded all cars for refractory repairs.

TK #4 / Cu 2508:

Screener is functioning. Continue on.

Inspected loading method and operators should not be stabbing material to try to break up. They need to take shallower scoops and the material will scoop fine.

Milling V 2046: N/A

Harrop Kiln / Al 3920:

Will need to get lit sometime this week.

Building 27 Belt Filter:

WOW for leaking vacuum pump. Continue with strikes. Glycol pump was pulled and will be sent out to be repaired.

PRODUCTION PRIORITIES:

Items 1-8 should be considered call out. I also attached what I think the lines should look like the next few weeks considering Nox scrubbing, quantities to make and shipments.

- 1) #6RC/East Pfaudler Continue with ICR 432v2LAQ see comment below on valve repairs
- 2) West Pfaudler Continue with Cu-0226 spheres both sizes need to get complete by December 14th so rate needs to be good (about 13 batches between both sizes)
- 3) #5 RC/Trimer Continue with 6081
- 4) South Precip/Dry Change over for S1-81 trial to start on Monday
- 5) Abbe/National Dryer Run as qualified labor is available use up all HF available
- 6) RC 1 Finish Al-5637 then go to refires, ART base next
- 7) MED 3 Finish A I-5637 then clean line for AL -3945 on Line and on RC 3 (check blank on line to RC)
- 8) RC 4 finish D-5206 (~15K), then clean line for Cu-0226
- 9) RC 2 when RC repair is done Dec 7 run out D-0768 then clean for Selexsorb

10) MED 1 - Finish prep for ART base

Équipment	7-Dec	14-Dec	21-Dec	28-Dec	Nox Control	
						Go ahead and clean 4 once
						done with D-5206. 12/ 15 Cu-
RC 4	Cu-0226	Cu-0226			Trimer	0226 ship date
RC 5	6081	6081	catoxid?	catoxid?	Trimer	keep 6081 hi priority
	ICR					
RC 6	432v2	ICR 419	ICR 424	ICR 424	СТО	
MED 1	Cleaning	ART base			Trimer	Get Ready for ART base
West						
Pfaudler	Cu-0226	D 4601	D 4601	D 4601	Trimer	
	MT					
MED 2	D0768	Selexsorb	Selexsorb		СТО	12/24 ship date Selexsorb
						Clean MED line for Al-3945 next
MED 3	AI-3945	AI-3945	AI-3945		СТО	week